

# SUPPORT BULLETIN

## SCZ-4 tape and SCZ-5 multifunction controllers, SKT and SKM subsystems

#26

1/22/92

Status: Technical communication only  
Subject: Legal errors for Exabyte 8500 and WangDat 2000 tape drives  
ECO#: N/A  
Assemblies: 500-479-00 (SCZ-4) and 500-495-00 (SCZ-5)  
Revisions: See content  
S/Ns: N/A

---

### Situation:

These new tape drives have some unique operational characteristics which will produce *test* errors under certain conditions. The purpose for this Support Bulletin is to advise you of legal errors which present no real problems.

### Legal errors:

1. Exabyte 8500 only:

MLTT\_FUNC will always fail at the beginning of the second pass as the 8500 will not become ready and online before second pass execution starts.

2. Exabyte 8500 and WangDat 2000:

Zetaco Reliability will intermittently report errors at EOT with a sense key of 300<sub>g</sub>.

### System Impact:

These characteristics pose no problems under the operating system.

### Action Required:

None, except to be aware of legal errors during testing.